

State of Utah

GARY R. HERBERT Governor

SPENCER J. COX Lieutenant Governor

Department of Environmental Quality

Amanda Smith Executive Director

DIVISION OF SOLID AND HAZARDOUS WASTE Scott T. Anderson Director M/041/0009 Peter Dennis Riding, Vice-Chair
Eugene Cole, DrPH
Jeff Coombs, MPH, LEHS
Mark Franc
Brett Mickelson
Amanda Smith
Shane Whitney
Dwayne Woolley
Scott T. Anderson
Executive Secretary

Kevin Murray, Chair

Solid and Hazardous Waste Control Board

June 12, 2014

Jimmy Lay Georgia-Pacific 1051 Hawthorne Circle Madison, GA 30650

RE: Compliance Evaluation Inspection

Georgia-Pacific Mill Site Landfill

Dear Mr. Lay:

The Georgia-Pacific Mill Site Class IIIb Landfill in Sigurd, Utah was inspected on May 14, 2014 by representatives of the Division of Solid and Hazardous Waste. Enclosed is the inspection checklist and copies of the inspection photographs.

During the inspection, it was documented that the gypsum piles were being removed and used as a soil amendment by Shaw Farms in Aurora Utah and as a component in the cement manufacturing by Ash Grove Cement Company in Lemington, Utah. This use was described to the Division in a letter dated July 16, 2013 from Georgia Pacific. During an inspection in March of 2012, the Division discussed the need for a compositing plan to be submitted and approved by this office. To date, no composting plan has been submitted for approval. Accordingly, please be advised that no further gypsum should be removed from the site until such time as Georgia Pacific submits and receives approval for a compost plan.

You are hereby requested to submit to this office on or before July 7, 2014 your written intent regarding this matter. If you have any questions, please call Doug Taylor at (801) 536-0240.

Sincerely,

Scott T. Anderson, Director

Division of Solid and Hazardous Waste

STA/DT/tjm

Enclosure: Inspection Report Checklist, Inspection Photographs

c: Bruce Costa, PhD., Health Director, Central Utah Public Health Dept.

(Over)


SOLID WASTE FACILITY INSPECTION REPORT CHECKLIST UTAH DIVISION OF SOLID & HAZARDOUS WASTE

Fac	cility Name Georgia Pacific Mill Site Class IIIb Landfill	County Sevier
Loc	cation 200 South State Street, Sigurd, Utah	
Insp	pection Date 5/14/2014 Time In 9:40 am	Time Out 10:10 am
Anı	utine Oversight	
	ticipants David Jolley - Geogia Pacific; Doug Taylor - DSHW	7
	LLOW UP INSPECTION NEEDED Yes No	
		es items reviewed)
1. PRI	E-INSPECTION REVIEW 1.1 Permit Review	
		3. SIGNS REQUIRED / PROPERLY POSTED
	1.2 Annual Report Review	3.1 Operating Days / Hrs.
	1.3 Previous Inspection Review	3.2 Directions & Procedure
	1.4 Facility Contacts Confirmed	3.3 Emergency Numbers
	1.5 Facility Contacted (if announced inspection)	3.4 List of Unacceptable Materials
	1.6 Local Heath Contacted	☐ 3.5 Other
	1.7 Other	
2 546		4. OPERATOR / REPRESENTATIVE / EMPLOYEES 4.1 On-site while open
Z. FAC	CILITY / OPERATIONAL CONTROLS 2.1 Litter	
		4.2 Training
Ш	2.2 Roads	☐ 4.3 Other
	2.3 Gate House Operations	
	2.4 Vectors	5. MONITORING
	2.5 Communications	5.1 Methane
		5.2 Random Inspections
	2.6 Recycling Area	5.3 Leachate
	2.7 Fugitive Dust Control	
	2.8 Waste Inspection Area	5.4 Ground Water
	2.9 Scavenging Control	5.5 Other
	2 10 On on Primin	
	2.10 Open Burning	6. DRAINAGE / EROSION 6.1 Water Run-on
	2.11 Fences, Gates, Locks, Access Control	
	2.12 Working Face	6.2 Water Run-off
	2.13 Leachate Collection System	6.3 Other
П	2.14 Other	7. PROPER STORAGE / ISOLATION / DISPOSAL
	2.17 Ould	7.1 Special Waste


DULID WADLE PACIFIED HOLECTION WEIGHT

	9.9 Deviation from Plans
7.3 Hazardous Waste	
7.4 Infectious Waste	9.10 Permit, Permit Application and Rules Available
	9.11 Other
7.5 Tires	
7.6 Dead Animals	10. MONITORING / SAMPLING / ANALYSIS RECORDS
	☐ 10.1 Explosive Gas Monitoring
7.7 Asbestos	☐ 10.2 Leachate Sampling & Treatment
7.8 Bulky Waste	10.2 Ecachate Sampling & Teathfort
7 1 20 2	☐ 10.3 Ground Water Sampling Results
7.9 Contaminated Soil	10.4 Other
7.10 Ash	10.4 cuiel
	AL CONCLUMENT DECORDS
7.11 Sludge	11. SPECIAL WASTE RECORDS 11.1 Lab Analysis Results
7.12 Other	
	11.2 Manifests
COVER	11.3 Treatment Certification
8.1 Daily - Soil	This Treatment Continuation
7 9.2 Daily Alemania	11.4 Paint Filter Test Results
8.2 Daily - Alternative	☐ 11.5 Onsite Treatment Documentation
8.3 Intermediate	11.5 Offsite Teatment Documentation
7 0.4 F. 1	☐ 11.6 Other
8.4 Final	
8.5 Vegetation	12. SPECIAL PERMIT REQUIREMENTS
8.6 Other	□ 12.1
8.0 Other	12.2
INSPECTION RECORDS 9.1 Random Inspection Report	12.3
3.1 Kandom hispection Report	
9.2 Gas Monitoring System	13. OTHER ITEMS
9.3 Surface Drainage Control	☐ 13.1 Notice of Inspections Form Completed and Signed
	□ 13.2
9.4 Daily Records	
9.5 Weight or Volumes	□ 13.3
	□ 13.4
9.6 Intermediate Cover	
9.7 Final Cover	13.5
9.8 Self Inspection (Quarterly) Reports	


Georgia-Pacific Mill Site Class IIIb Landfill Inspection Photographs – May 14, 2014




Excavation face at the Mill Site gypsum pile



Screen at the Mill site pile



Excavation at the south portion of the Mill site pile



South gypsum pile

Page 2 of 2